



NOTICE



This product has had a specification change that may affect compatibility if pairing with legacy equipment.

We have replaced the #891 Luer Slip Connector with an #8974 bayonet connector, pursuant to the FDA's Standards for Small-Bore Connectors (ISO 80369-1:2010 and ISO 80369-20:2015).



For more information about this change, visit www.adctoday.com/connector-update or scan the QR code.